

SAFE WORK PROCEDURE

Personal Protective Equipment that MUST be worn when working with a Gizmo 3D printer includes:





Pre-operational Safety Checklist:

$\sqrt{}$	Bend your knees when lifting or moving the	Put a sign up on the wall that w
	printer to avoid an injury if it's heavy.	passing by the machine not to
		or unaurod/wat ragin printa

- The work area should be clean and free of rubbish and other obstacles.
- Ensure you have had instruction and training to use the equipment correctly and safely.
- varns people touch the resin or uncured/wet resin prints.
- Always read the latest Material Safety Data Sheet (MSDS) of the resin you will be using before using it.
- Set up an eyewash station and ensure anyone using the machine knows where it is.

Operating Safety Precautions Checklist:

/	Use in a well-ventilated area.	\	Wipe up any spilled resin right away to avoid slipping.
\checkmark	Wash hands thoroughly after handling.		
/	Use UV resistant safety glasses when work-	V	Take care when working with sharp tools to take prints off of the build plate or removing

supports.

Do not dispose of resin the sink/drain. Never touch the electronics of the machine.

ing with the machine and resin to avoid UV

exposure and resin splash to your eyes.

Wear gloves if you should ever need to Do not place fingers or tools inside the handle wet resin prints or touch wet resin. printer while parts are building.

Safe work procedure approved by:									
Manager's name	Manager's signature	Date:							